

Header redesign for B-42 softener water discharge for Chlorine Dioxide Injection.



Disconnect existing header and add elbow to new header, blanking old header connection.

Add new supply header



Disconnect existing header and add elbow to new header, blanking old header connection. Also add 1" injection port and sample port to new header.

Reconnect monitor and hot water heater piping



Add new supply header to include 1" eyewash/water heater connection